

CROSS BORDER INTEROPERABILITY – CORRIDOR OVERVIEW

	Region	Safety certificate	Authorisation of vehicles	Driver certification	Language	Specification of language level	Tail signal
Legal basis (EU level)	EU	2004/49/EC, 1158/2010EC	2001/16EC, 2008/57/EG, 2014/38/EU	2007/59/EC, 2014/82/EC	2014/82/EC	B1 (Proposal for simplification under discussion)	TSI Operations (EU) 2015-995 chapter 4.2.2.1.3.2
National laws and regulations CZ	CZ	Act on rail system No. 266/1994 Coll.	Act on rail system No. 266/1994 Coll., Government Order No. 133/2005 Coll., on the technical requirements for operational and technical interoperability of the trans-European rail system, decree No. 352/2004 Coll., on the interoperability of the European rail system	Act on rail system No. 266/1994 Coll., decree No. 16/2012 Coll., decree No. 101/1995 Coll.	Czech, decree No. 16/2012 Coll.	B1	National law: decree no. 173/1995 Coll., Issuing the Railway Transportation Rules
National laws and regulations SK	SK	Act No. 513/2009 Coll. implementing the Directive 2004/49/EC Commission Regulation No. 1158/2010 EC	Act No. 513/2009 Coll. implementing the Directive 2008/57/EC	Act No. 514/2009 Coll. implementing the Directive 2008/59/EC	Act No. 514/2009 Coll. implementing the Directive 2008/59/EC	B1	Commission Decision No 2012/757/EC
Topic Responsibility	Region	Safety certificate	Authorisation of vehicles	Driver certification	Language	Specification of language level	Tail signal
		NSA	NSA	NSA	IM	IM	IM
Border crossing		State of play regarding cross border interoperability: rule / document valid / required on the specific section					
<u>Horní Lideč</u> – border	CZ	Safety certificate B is required	Act on rail system No. 266/1994 Coll.	Act on rail system No. 266/1994 Coll., decree No. 16/2012 Coll., decree No. 101/1995 Coll.	Czech / Slovak	B1	Commission Decision No 2012/757/EC Both tailplates or taillights are accepted - marking of the train is an issue of RU
Border – <u>Púchov</u>	SK	Act No. 513/2009 Coll. implementing the Directive 2004/49/EC Commission Regulation No. 1158/2010 EC	Act No. 513/2009 Coll. implementing the Directive 2008/57/EC	Act No. 514/2009 Coll. implementing the Directive 2008/59/EC	Slovak / Czech Act No. 514/2009 Coll. implementing the Directive 2008/59/EC Local cross border agreement between IMs	B1	
<u>Mosty u Jablunkova</u> – border	CZ	Safety certificate B is required	Act on rail system No. 266/1994 Coll.	Act on rail system No. 266/1994 Coll., decree No. 16/2012 Coll., decree No. 101/1995 Coll.	Czech / Slovak	B1	Commission Decision No 2012/757/EC Both tailplates or taillights are accepted - marking of the train is an issue of RU
Border – <u>Čadca</u>	SK	Act No. 513/2009 Coll. implementing the Directive 2004/49/EC Commission Regulation No. 1158/2010 EC	Act No. 513/2009 Coll. implementing the Directive 2008/57/EC	Act No. 514/2009 Coll. implementing the Directive 2008/59/EC	Slovak / Czech Act No. 514/2009 Coll. implementing the Directive 2008/59/EC Local cross border agreement between IMs	B1	